



2001-2006 Mini Cooper MAP Sensor Replacement

This video guide will teach you how to replace a MAP sensor in a 2001-2006 Mini Cooper. The instruction ends at 11:41 and continues on to the thermostat.

Written By: Sydtracked





TOOLS:

- [10mm Wrench](#) (1)
- [Flathead 3/32" or 2.5 mm Screwdriver](#) (1)
- [1/4" Ratchet Extension](#) (1)
- [3mm Hex Key \(or Bit\)](#) (1)
- [10mm Socket](#) (1)
- [Socket Wrench](#) (1)



PARTS:

- [MAP Sensor](#) (1)

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-15 05:26:22 AM.